

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1567
NNE
> 1
1.984 mi.
10477 ft.

RESIDENCE - P
1789 EAST 7TH ST
BROOKLYN, NY

NY Spills S123663063
N/A

Relative:
Higher

Actual:
24 ft.

SPILLS:

Name: RESIDENCE - P
Address: 1789 EAST 7TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1900731 / 2019-09-10
Facility ID: 1900731
Facility Type: ER
DER Facility ID: 537902
Site ID: 586567
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2019-04-22
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2019-04-22
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2019-04-22
Spill Record Last Update: 2019-09-10
Spiller Name: Not reported
Spiller Company: HOMEOWNER
Spiller Address: Not reported
Spiller Company: 999
Contact Name: WILLIAM DEPAOLO
DEC Memo: "04/22/19 - Lakhani A Petro technician discovered that the 275 gallon #2 fuel oil AST at the property developed a leak. The bottom of the tank is wet. However, the tank is not actively leaking. Drip pans were placed underneath the tank to catch the oil. No oil has impacted the basement floor. The owner, William Depaolo (718-376-6264), refused an emergency pump out. DEC Lakhani spoke to William and informed his that it may be in his best interest to pump out the tank immediately. Petro Joshua Nieves sent photos of the tank. Three drip pans are oriented beneath the tank and contain small amounts of oil. DECPiper spoke with Ann Marie with Milro. They have completed the tank replacement. Spill closed."

Remarks: "being collected into pan. Under 1 gallon spilled."

All Materials:

Site ID: 586567
Operable Unit ID: 1334249
Operable Unit: 01
Material ID: 2343551
Material Code: 0001A
Material Name: #2 fuel oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported